

LIFE THREATENING DEFICIENCIES

HCV CORRECTION TIMEFRAME 24 HOURS, IF OCCUPIED		O=Owner	T=Tenant
DEFICIENCY (INSPECTABLE ITEM)	DEFICIENCY DESCRIPTION	O	T
Call-For-Aid System	System is blocked, or pull cord is higher than 6 inches off the floor. System does not function properly.		
Carbon Monoxide Alarm	Carbon monoxide alarm is missing, not installed, or not installed in a proper location.* Carbon monoxide alarm is obstructed. Carbon monoxide alarm does not produce an audio or visual alarm when tested.		
Chimney	A visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged. Chimney exhibits signs of structural failure.		
Clothes Dryer Exhaust Ventilation	Electric dryer transition duct is detached or missing. Gas dryer transition duct is detached or missing. Electric dryer exhaust ventilation system has restricted airflow. Dryer transition duct is constructed of unsuitable material. Gas dryer exhaust ventilation system has restricted airflow.		
Door - Entry	Entry door is missing.		
Door - Fire Labeled	Fire Labeled door is missing.		
Egress	Obstructed means of egress. Sleeping room is located on the 3rd floor or below and has an obstructed rescue opening. Fire escape access is obstructed.		
Electrical - Conductor, Outlet, and Switch	Outlet or switch is damaged. Exposed electrical conductor. Water is currently in contact with an electrical conductor.		
Electrical - Service Panel	The overcurrent protection device is damaged.		
Exit Sign	Exit sign is damaged, missing, obstructed, or not adequately illuminated.		
Fire Escape	Fire escape component is damaged or missing.		
Fire Extinguisher	Fire extinguisher pressure gauge reads over or under-charged. Fire extinguisher service tag is missing, illegible, or expired. Fire extinguisher is damaged or missing.		
Flammable and Combustible Item	Flammable or combustible item is on or within 3 feet of an appliance that provides heat for thermal comfort or a fuel-burning water heater. OR Improperly stored chemicals.		
Guardrail	Guardrail is missing or not installed.* Guardrail is not functionally adequate.		
Heating Ventilation and Air Conditioning (HVAC)	The inspection date is on or between October 1 and March 31 and the permanently installed heating source is not working or the permanently installed heating source is working and the interior temperature is below 64 degrees Fahrenheit.* Unvented space heater that burns gas, oil, or kerosene is present.* Combustion chamber cover or gas shutoff valve is missing from a fuel burning heating appliance. Fuel burning heating system or device exhaust vent is misaligned, blocked, disconnected, improperly connected, damaged, or missing.		
Leak - Gas/Oil	Natural gas, propane, or oil leak.		
Mold-Like Substance	Presence of mold-like substance at extremely high levels is observed visually.		
Smoke Alarm	Smoke alarm is not installed where required.* Smoke alarm is obstructed. Smoke alarm does not produce an audio or visual alarm when tested.		
Sprinkler Assembly	Sprinkler head assembly is encased or obstructed by an item or object that is within 18 inches of the sprinkler head. Sprinkler assembly component is damaged, inoperable, or missing and it is detrimental to performance. Sprinkler assembly has evidence of corrosion. Sprinkler assembly has evidence of foreign material that is detrimental to performance.		
Structure	Structural system exhibits signs of serious failure.		
Toilet	Only 1 toilet was installed, and it is missing.		
Water Heater	Chimney or flue piping is blocked, misaligned, or missing. Gas shutoff valve is damaged, missing, or not installed.		